## PROJECT INTELLIGENCE

On the St. Croix River Crossing

Si Katara President/Co-Founder






# AN EXPLOSION OF NEW DATA GATHERING TECHNOLOGIES



## NEW APPROACHES OFFER PROMISE BUT EXECUTION IS VERY COMPLEX





# E-CONSTRUCTION IS AN IMPROVEMENT BUT LIMITED IN SCOPE

Not enough capabilities























#### Inspector's Daily Report

Photographs



Taken at 8:00 am, Thursday, October 19, 2017

Temperature Differentials

#### Contractor

Kiewit-Hoffman

#### **Work Location**

WA2A: 140th Ave SE to NE 24th St



Taken at 8:02 am, Thursday, October 19, 2017

Tree that fell across the silt fence at Sweeper Site.

#### Contractor

Kiewit-Hoffman

#### **Work Location**

WA2A: 140th Ave SE to NE 24th St



Taken at 8:03 am, Thursday, October 19, 2017

Taken at 8:11 am Thursday October 19 2017

Storm water conveyance system hose with a leak.


#### Contractor

Kiewit-Hoffman

#### **Work Location**

WA2A: 140th Ave SE to NE 24th St





### ST. CROIX CROSSING



### **REDUCE RISK WITH A BETTER SAFETY NET**

